Release Notes MC18 Android Lollipop - Fusion 5.00.0.0.022 for BSP 01.11.02.X.00

Contents

Description

Fusion is a suite of software, which allows for WLAN connectivity, configuration, status reporting, and diagnostics.

This is a release of **MC18-L-011102-X-00.zip** for MC18 Android Lollipop. This release supports ETSI RE-D compliance.

This is a release of Fusion 22R for Android Lollipop. This release corrects the following issues:

- SPR 31955 - Resolved an issue in which Cisco AnyConnect client does not connect to the server due to incorrect IP address state reported by WLAN.
- SPR 30157 - Fixed an issue wherein the device spontaneously reboots at times.
- SPR 30458 - Resolved an issue in which toggling Wi-Fi ON/OFF repeatedly causes a Kernel Panic and reboot.
- SPR 30259 - Fixed an issue wherein device encounters random reboots while roaming in 802.1x infrastructure.
- SPR 31247 - Fixed an issue in which the WLAN radio fails to roam sometimes when Fast Transition (802.11r) is enabled on the infrastructure.
- SPR 30135 - Resolved an issue in which WLAN radio does not roam to DFS channels that resulted in stickiness or disconnect.
- SPR 31036 - Resolved issue in which MC40 was experiencing high degree of disruption to voice quality during VOIP calls.
- SPR30025 - Fixed an issue wherein the device experience audio disruption during VOIP call.
- SPR 29874 - Resolved an issue in which pings to the device were lost for 5 to 10 seconds sometimes after connecting to the network.
- Added Support for latest ETSI RED compliance.

Device Compatibility

This software release has been approved for use with the following Zebra devices.

Device	Operating System
MC18	Android Lollipop BSP 01.11.02

Installation Instructions

NOTE: Prior to installation, ensure that you are currently running an approved version of the Operating System from the table above. Otherwise, visit https://www.zebra.com/us/en/support-downloads

Manual Installation:

1. Copy MC18-L-011102-X-00.zip to the sdcard.

2. Boot the device into recovery mode.

3. In recovery mode select "apply update from sdcard" option

4. Select the MC18-L-011102-X-00.zip from sd card to install.

Downloadable Software Included in this Release

Filename	Description
MC18-L-011102-X-00.zip	OTA package update for Fusion Release